APR 25 2001

INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573

Assigned Recall No. <u>91E-918</u> by the National Highway Traffic Safety Administration

Part 573 Report Date: April 23, 2001

MANUFACTURER: Advanced Engine Management, Inc. (AEM)

MANUFACTURER CONTACT: Mr. Abraham M. Rudy
Counsel for AEM

FAX: 310-550-7191

SUBJECT: 3,000 air bypass valves Part Nos. 20-401, 20-402, and 20-403, sold between August 1, 2000, and January 31, 2001, for installation on passenger vehicles to prevent ingestion of water into the engine. The valves are constructed of two plastic pieces sonically welded with a silicon diaphragm and foam spring. The weld seam can crack under high stress loads and the valve's internal diaphragm and spring may be ingested into the throttle body, which in turn, may cause the throttle to stick open. If the throttle is unable to return to the closed position, the driver may lose control of the vehicle possibly resulting in a vehicle crash.

This is an <u>initial</u> acknowledgment for this recall. A formal acknowledgment letter will be forthcoming shortly. After our review of your report and associated documents, we may have additional comments or concerns.

NOTIFICATION TO PURCHASERS

We have reviewed AEM's proposed owner notification letter and it does not meet the requirements of 49 CFR Part 577.

Under requirements of 49 CFR Part 577, the opening statement shall read "This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act." The following sentence states "[Manufacturer's name] AEM has decided that a defect which relates to motor vehicle safety exists in [identify the vehicles or motor vehicle equipment]." Please revise the owner letter prior to mailing to the customers.

The rest of your package is acceptable and AEM can begin notification as soon as it is ready.

If you have any questions, please call:

Kelly Schuler, Safety Defect Analyst or Jonathan White, Chief at (202) 366-5227 or by FAX (202) 366-7882
Defect and Recall Information Analysis Division

Faxed on 4/25/01

MAY 10 2001

Abraham M. Rudy, Esq. Counsel for AEM Weismann, Wolf, et. al. 9665 Wilshire Boulevard Beverly Hills, CA90212-2345 N8A-11kjs 01E-018

Dear Mr. Rudy:

We have reviewed Advanced Engine Management, Inc's (AEM) Defect Information Report dated April 23, 2001, submitted in accordance with 49 CFR Part 573, "Defect and Noncompliance Reports." This recall involves 3,000 air bypass valves Part Nos. 20-401, 20-402, and 20-403, sold between August 1, 2000, and January 31, 2001, for installation on passenger vehicles to prevent ingestion of water into the engine. The valves are constructed of two plastic pieces sonically welded with a silicon diaphragm and foam spring. The weld seam can crack under high stress loads and the valve's internal diaphragm and spring may be ingested into the throttle body, which in turn, may cause the throttle to stick open. If the throttle is unable to return to the closed position, the driver may lose control of the vehicle possibly resulting in a vehicle crash. The assigned NHTSA identification number for this campaign is 01E-018.

AEM is responsible for the remedy of this equipment from this date forward, regardless of age or ownership.

QUARTERLY REPORTS

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. The calendar quarter began on April 1 and ends on June 30, 2001. Since owner notification will begin during this time period, your first quarterly report is due in this office by July 30, 2001.

The following chart provides due dates for each of the six quarterly reports.

QUARTER	QUARTER BEGINS	QUARTER ENDS	<u>DUE DATE</u>
1st Quarter	April 1, 2001	June 30, 2001	July 30, 2001
2 nd Quarter	July 1, 2001	September 30, 2001	October 30, 2001
3rd Quarter	October 1, 2001	December 31, 2001	January 30, 2002
4 th Quarter	January 1, 2002	March 31, 2002	April 30, 2002
5 th Quarter	April 1, 2002	June 30, 2002	July 30, 2002
6th Quarter	July 1, 2002	September 30, 2002	October 30, 2002

If you have any questions, please contact Mrs. Kelly Schuler at (202) 366-5227 or fax at (202) 366-7882.

Sincerely,

151

Jonathan D. White, Chief Defect and Recall Information Analysis Division Office of Defects Investigation Safety Assurance

NHTSA:NSA:ODI NSA-11KSchuler:65227:5/10/01 I:\react\ack\2001\01ack_equ&tire\01e018.ack.wpd